

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	638	blind near3 (rivet\$5 fastener).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/02/08 16:26
L2	16	1 and (measur\$5 sens\$5 detect\$5 determin\$5 calculat\$5) near3 (strain stress load pressure force).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/02/08 16:27
L3	2	2 and (piezo\$5)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/02/08 16:27
L4	4150	blind near3 (rivet\$5 fastener)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/02/08 16:26
L5	227	4 and (measur\$5 sens\$5 detect\$5 determin\$5 calculat\$5) near3 (strain stress load pressure force)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/02/08 16:27
L6	11	5 and (piezo\$5)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/02/08 16:28

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	1332	blind near2 fastener	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/02/08 16:01
L2	203	1 and (sensor detector transducer measur\$5)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/02/08 15:45
L3	160	2 and (compress\$5 deform\$5 bend\$5)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/02/08 15:41
L4	149	3 and (load force pressure strain stress)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/02/08 15:41
L5	85	4 and (tool)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/02/08 15:41
L6	38	5 and (setting)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/02/08 15:42
L7	18	6 and (sensor detector transducer gauge)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/02/08 15:59
L8	10	"5661887"	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/02/08 16:08
L9	8	8 and (sensor detector transducer gauge).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/02/08 16:00
L10	1	9 and (blind near2 fastener)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/02/08 16:01
L11	1	(measur\$5 sens\$5 detect\$5 determin\$6 calculat\$5 transducer) near3 (load force strain stress pressure) near3 (blind) near3 (fastener rivet\$5).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/02/08 16:15

L12	13	(measur\$5 sens\$5 detect\$5 determin\$6 calculat\$5 transducer) near3 (load force strain stress pressure) near3 (blind) near3 (fastener rivet\$5)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/02/08 16:16
L13	638	(blind) near3 (fastener rivet\$5).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/02/08 16:16
L14	16	13 and (measur\$5 sens\$5 detect\$5 determin\$6 calculat\$5 transducer) near3 (load force strain stress pressure).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/02/08 16:17

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	638	blind near3 (rivet\$5 fastener).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/02/08 16:26
L2	16	1 and (measur\$5 sens\$5 detect\$5 determin\$5 calculat\$5) near3 (strain stress load pressure force).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/02/08 16:27
L3	2	2 and (piezo\$5)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/02/08 16:27
L4	4150	blind near3 (rivet\$5 fastener)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/02/08 16:26
L5	227	4 and (measur\$5 sens\$5 detect\$5 determin\$5 calculat\$5) near3 (strain stress load pressure force)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/02/08 16:27
L6	11	5 and (piezo\$5)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/02/08 16:28